



## **Service Bulletin**

**No. :** MZ01-025

**Date:** April 25, 2007

---

**Model:** SR-14, SR-18, SR-19, AV9000

**Subject:** Improvement for backup time of memory

**Symptom:** The backup memory becomes short.

**Solution:** Replace capacitor CY30 with the improved type.

**Parts:**

Ref#	Description	Part Number
CY30	1F / 5.5V	EX10500540

**Serial Number Range:**

Per customer claim.

---

**CONFIDENTIALITY NOTICE:**

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.