



Service Bulletin

No. : MZ01-033

Date: December 4, 2006

Model: SA-1

Subject: Correction of part description (POS. NO W502)

Symptom: The part description for POS.NO W502 mentioned on page 1-23 of the service manual is incorrect.

Solution: See the corrected information below.

Ref #	INCORRECT		CORRECT	
	Description	Part Number	Description	Part Number
W502	FFC 19PIN 120MM1.25MM PITCH	YU29120530	FFC 29PIN 120MM1.25MM PITCH	YU29120530

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility is will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.