

marantz® SERVICE BULLETIN		Date: 15-May.-2003	Model: SR4200
		Page: 1 / 1	REF.NBR: MZ03-013
Circulation:		Application:	
x for information customer complaint in case of service mandatory		See Below	
		Subject: Pro Logic II movie and Pro Logic II music mode can't be chosen.	
		Int.ref:	

[PHENOMENON]

When Dolby Digital 2ch is inputted with Digital, the Dolby mode can't be chosen.

[SOLUTION]

Replace MICRO PROCESSOR (**IC71**) on the **FRONT CIRCUIT BOARD**.

[NECESSARY PART]

POS.NO **IC71** ***HC108300R**

(FACTORY PART NO. HVIANAM1326AT / HVITMP87PS71AF)

[REMARKS]

The countermeasure apply to this claim only.

The production of SR4200 has been finished.

Approved by **S.NAGAO**

Written by