



Service Bulletin

No.: MZ06-010


Date: December 21, 2006

Model: SR4600


Subject: Correction of the Service Manual and Schematic Diagram.

Symptom: The SCHEMATIC DIAGRAM mentioned in the SR4600's Service Manual is incorrect. (Service Manual pages 9 and 10)

Solution: SR4600 service manual (part no.90M42BW855010) INPUT & DSP PWB (1/3) schematic page 9 and 10 has been updated. See the following pages for details.



CONFIDENTIALITY NOTICE:



Serial Number Range:

ΑII