



**Service Bulletin** 

**No. :** MZ07-056 **Date:** May 16, 2007


Model: SR4001, SR5001


Subject: Part Specification Change: OPT/COAX Complex Jack (both

TX/RX)

**Symptom:** The manufacturer has discontinued production of the current parts.

**Solution:** 1. JK11, JK12 (RX) and JK14 (TX) on the INPUT PWB are the parts whose specifications have been changed this time.








## **CONFIDENTIALITY NOTICE:**

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.

2. Due to the configuration difference, the new parts are incompatible with the old ones. Please note that the INPUT PWB and REAR PANEL have to be replaced.









## Parts:

| OLD<br>NEW | POS.<br>NO.  | VERS.<br>COLOR | PART NO.<br>(FOR EUR) | PART NO.<br>(MZ) | PART NAME | DESCRIPTION  |
|------------|--------------|----------------|-----------------------|------------------|-----------|--|
| OLD        | JK11<br>JK12 |                | 90M-YT004060R         | 90M-YT004060R    | TERMINAL  | YKC22-0735N<br>Factory code no.HJS9U002Z           |
| NEW        | JK11<br>JK12 |                | 90M-YT005330R         | 90M-YT005330R    | TERMINAL  | YKC22-0836V<br>Factory code no.CJS9U013Z           |
| OLD        | JK14         |                | 90M-YT004070R         | 90M-YT004070R    | TERMINAL  | YKC22-0734N<br>Factory code no.HJS9U001Z           |
| NEW        | JK14         |                | 90M-YT005340R         | 90M-YT005340R    | TERMINAL  | YKC22-0835V<br>Factory code no.CJS9U012Z           |
| OLD        | 21           | /U1B           | nsp                   | nsp              | PANEL     | SR4001 REAR PANEL/U<br>Factory code no. CKF2A308Z  |
| NEW        | 21           | /U1B           | nsp                   | nsp              | PANEL     | SR4001 REAR PANEL/U<br>Factory code no. CKF12A308Z |
| OLD        | 21           | /U1B           | nsp                   | nsp              | PANEL     | SR5001 REAR PANEL/U<br>Factory code no. CKF7A308Z  |
| NEW        | 21           | / <b>U1B</b>   | nsp                   | nsp              | PANEL     | SR5001 REAR PANEL/U<br>Factory code no. CKF17A308Z |

## **Serial Number Range:**

SR4001: MZ0107XX008951~ SR5001: MZ0107XX013151~

## **CONFIDENTIALITY NOTICE:**

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.