



## **Service Bulletin**

**No. :** MZ07-060

**Date:** May 21, 2007

---

**Model:** SR4001, SR5001 SR7001, SR8001

**Subject:** A component configuration change: TUNER MODULE and FM ANTENNA only for the US version.

**Symptom:** The configuration of the FM Antenna Terminal was changed from the APL/F common connector to the F Connector.


**Solution:** 1. Change of TUNER MODULE  
POS.NO. 20 SR4001, SR5001  
POS.NO. 60 SR7001, SR8001

---

#### **CONFIDENTIALITY NOTICE:**

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.

## 2. Change of accessory FM Antenna



**OLD: TUNER MODULE**  
**PART NO. 90M-AV000410R**



**NEW: TUNER MODULE**  
**PART NO. 90M-AV000570R**



**OLD: FM ANTENNA**  
**PART NO. 90M-ZA000210R**



**NEW: FM ANTENNA**  
**PART NO. 90M-ZA000290R**



### CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.

## Parts:

### [NECESSARY PARTS]

OLD NEW	POS. NO.	VERS. COLOR	PART NO. (FOR EUR)	PART NO. (MZ)	PART NAME	DESCRIPTION
OLD	20 20 60 60	SR4001/U1B SR5001/U1B SR7001/U1B SR8001/U1B	nsp	90M-AV000410R	TUNER	TUNER MODULE (USA)  Factory code no. CNVMB014MA08L
NEW	20 20 60 60	SR4001/U1B SR5001/U1B SR7001/U1B SR8001/U1B	nsp	90M-AV000570R	TUNER	TUNER MODULE (USA)  Factory code no. CNVMB014MA08LS
OLD	-	-	nsp	90M-ZA000210R	ANTENNA	ANT FM WIRE (PIGTAIL)  Factory code no. CSA1A007
NEW	-	/U1B	nsp	90M-ZA000290R	ANTENNA	FM 1 POL ANT (UL)  Factory code no. CSA1A033Z

## Serial Number Range:

This component configuration change has been already implemented on the following serial numbers:

SR4001: MZ0107XX010801~  
 SR5001: MZ0107XX015221~  
 SR7001: MZ040716006501~  
 SR8001: MZ040717002802~

### CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.