



**Service Bulletin** 

**No. :** MZ07-089 **Date:** October 2, 2007

Model: SR4002, SR5002

**Subject:** Software Update Information. \* This update is for only following minor problem, and not required on all units you service.

**Symptom:** 1. When the unit is in Service Mode, the serial number is not displayed correctly.

2. When the volume is being controlled, the OSD may display unnecessary letters.

**Solution:** 1. The microprocessor firmware must be updated. Firstly, please check the current firmware version in reference to "4. SERVICE MODE" in the Service Manual. After the correction, please check the firmware version. 2. Update Firmware and the part number Firmware Ver: SR5002\_070823\_1.mot For information on how to rewrite the firmware, please refer to "6. UPDATE FIRMWARE" in the Service Manual.

## Parts:

Ref#	Description	Part Number
Firmware	SR5002_070823_1.mot	00M32CW499A02

Check the firmware version. If it is yet to be updated, please perform the latest update.

Firmware Version:

Ref No.	DATE	MAIN	DSP(Flash ROM)
MZ07-089	2007.10.01	V0708231	DSPROM 061208

## **CONFIDENTIALITY NOTICE:**

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.

## Serial Number Range:

Model	Servicing necessary	Already updated
SR5002	~MZ0007XX004320	MZ0007XX004321~
SR4002	~MZ0007XX002720	MZ0007XX002721~

## **CONFIDENTIALITY NOTICE:**

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.