



Service Bulletin

No. : MZ09-003 **Date:** February 5, 2009

Model: SR4001, SR4002, SR4003, SR5001, SR5002, CD5003

Subject: Correction of the Service Manual, electrical parts list.

Symptom: The REGULATOR (IC) part number mentioned on the Service

Manual is not correct.

Solution: Service manual correction.

Parts:

REGULATOR PWB of SR4001, SR4002, SR4003, SR5001, SR5002


OLD NEW	POS. NO.	VERS. COLOR	PART NO. (MZ)	PART NAME	DESCRIPTION
OLD	IC87		00MHC3991209F	IC	KIA7912PI Factory cord: HVIKIA7912PI
NEW	IC87		00D2631099022	IC	KIA7912PI-U/P Factory cord: HVIKIA7912PI

POWER PWB of CD5003

OLD NEW	POS. NO.	VERS. COLOR	PART NO. (MZ)	PART NAME	DESCRIPTION
OLD	IC93		00MHC3991209F	IC	KIA7912PI Factory cord: HVIKIA7912PI
NEW	IC93		00D2631099022	IC	KIA7912PI-U/P Factory cord: HVIKIA7912PI

CONFIDENTIALITY NOTICE:

The difference of package dimensions between 00MHC3991209F and 00D2631099022.



Serial Number Range:

ΑII