



Service Bulletin

No. : MZ10-031

Date: November 2, 2010

Model: SR6005

Subject: Issuing of the initial firmware for DFW (D&M Firmware Writer).

This is Information only.

Symptom: The initial firmware is now available.

Solution:

METHOD OF UPDATING via RS232C.

We will supply the following program files for updating the subject model.

Please refer to the supplied Instruction Manual for updating.

DFW software:

DFW_0004_SR6005_(Rev.1.0.6).exe:

Firmware Update Program

DFW_0004_SR6005_Rev.1.0.6_manual_EN.pdf:

Instruction Manual for Firmware Update

Firmware:

SR6005_DM10-031.zip

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.

Firmware version

	Name	Version
1	Main	83.51
2	Main FBL	00.11
3	Sub	24.13
4	Sub FBL	05.01
5	DSP	59.08
6	Audio PLD	04.02
7	USB	705
8	OSD CFG	200912070011
9	OSD PRG	201006251007
10	OSD DAT	201006251009

Serial Number Range:

All

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.