

marantz® SERVICE BULLETIN		Date: 8-Nov-2002	Model: SR7000
		Page: 1 of 1	REF.NBR: MZ02-018
Circulation:		Subject:	
Application:		Correction of part number (POS. NO. LB51).	
x for information customer complaint in case of service mandatory			
Service Manual			

[PHENOMENON]

The part number for POS.NO. LB51 mentioned on page 74 of the service manual (320J855010, 3120 785 22280) is incorrect.

13. ELECTRICAL PARTS LIST (page 74)

POS. NO	VERS. COLOR	PART NO. (FOR PCS)	DESCRIPTION	PART NO. (MJI)
LB51	/K,N,S	---	MAINS TRANSF EI48-20T 220V 50Hz	TS14831020

[CORRECTION]

The correct part number is;

POS. NO	VERS. COLOR	PART NO. (FOR PCS)	DESCRIPTION	PART NO. (MJI)
LB51	/N,S,	9965 000 03409	MAINS TRANSF 230V 50Hz	TS14831030
	/K	---	MAINS TRANSF 220V 50Hz	TS14831020