



Service Bulletin

No. : MZ09-153


Date: February 2, 2010

Model: SR8002, SR7002

Subject: Change in the "UL mark" on the rear panel because the expiration date of the "safe standard of Canada (CSA)" expired.

This is for information only.

Details: The listed models were authorized under "UL1492" and "CSA22.2 No. 1-04". However, the expiration date of "CSA22.2 No. 1-04" expired at 31st of December 2009. Therefore, we changed the "UL mark" on the rear panel from "a mark for both of UL and CSA" to "a new mark for UL only".



Serial Number Range:

We will apply the above modification to models in the following serial numbers.
(Full-digit)

Model	Serial Number
SR8002	MZ111004005351 ~
SR7002	MZ111002009691 ~

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.