



Service Bulletin

No. : MZ02-030

Date: December 5, 2006

Model: SR8200, SR9200

Subject: The Dolby Digital sound is interrupted.

Symptom: When playing back certain DVD discs such as: Pearl Harbor, Jurassic Park 3, Beast Monster and Stuntman DVD the Dolby Digital sound is interrupted.

Solution: The version of the Dolby encoder was changed to cope with Dolby EX.

Update the CPU (QU01) and DSP (Q671) IC's firmware to the following version (or the latest version).

1. The version for the CPU (QU01): 011225 01
2. The version for the DSP (Q671) : CD 07 01030102: CD 03 01010302

Refer to pages 97 and 98 for the firmware update procedure.

Parts:

Ref#	Description	Part Number
NA	Firmware update Disc	*SR9200CDR

Serial Number Range:

This improvement has been done in the production after the Lot number MZxxxxxx06xxxx and later. (SR9200/U1B/S1G) the Lot number MZxxxxxx04xxxx and later. (SR8200/U1B/S1G). The Lot number is mentioned the serial number label on the rear panel. (ex.MZxxxxxx06xxxx).

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility is will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.