



Service Bulletin
No. : MZ00-US02
Date: December 13, 2006

Model: SR9600

Subject: Service manual part correction.

Symptom: The part number listed in the service manual or the FM Antenna is incorrect. The part number listed in the manual is for the setup microphone (MIC MC-10).

Solution: Refer to the parts section below for the FM Antenna part number.

Parts:

Ref#	Description	Part Number
Z007	Antenna, FM	3950028003

Serial Number Range:

All

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.