



**Service Bulletin** 


**No. : MZ07-051 Date:** April 24, 2007

Model: ST7001

Subject: Software Update

**Symptom:** Through RS232C, XM SONG TITLE only displays 15 characters. Based on ST7001 specification, it can display 16 characters.

**Solution:** Update the Main Microprocessor firmware to version [XM MP003]. Please refer to the service manual ST7001/U1B page 3 to 9 for the procedure.



Before stating, check the firmware version. It can be confirmed through the "B.SERVICE MODE". Refer to the service manual ST7001/U1B on page 2 for the firmware procedure.

## **CONFIDENTIALITY NOTICE:**

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.

## Parts:

Ref#	Description	Part Number
NA	Application Software	FMC8FX.zip
NA	For Writing data "st7001xm_MP003.mhx"	st7001xm_MP003.zip

Attention: Don't start updating from zipped file. Please copy the zipped file onto your PC and unzip the file to use it.

## Serial Number Range:

The ST7001/U1B update applies to MZ000651xxxxx and earlier. This improvement has already been done in production from serial number MZ000716xxxxx and later.

## **CONFIDENTIALITY NOTICE:**

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.