

NAGRA-V / NAGRA V-PP SOFTWARE BULLETIN FOR THE VERSION V3.10.

This update requires changing the box motherboard EPROM (P/N 9131 300 020) and installing new software (via HDD) for the PC of the deck motherboard.

The time code EPROM compatible with this version for the CPU remains the version V 3.10

NEW:

The RS422 protocol has been updated to handle the management of folders and copies when working with the new **Navcom V1.2** software.

IMPROVEMENTS:

Low bat: Modification of the low bat voltage security level when using Lithium-Ion batteries, this to improve the general overview of the remaining time. This will also improve the lifetime of the battery pack.

Renaming or erasing of a destination folder for copying is now possible if “EXIST ERR” appears.

Scene: The scene numbering now accepts Alpha-numeric characters for all digit positions.

NuBITS: The character “\$” has been removed.

Time code stamp: For a new recording during a copy of another index, the time code start could be previously have been wrong.

The appearance of the sub menus “NEW” and “COPY” in the “Folders” menu has been reversed.

The selection of “NEW” and “RENAME” features in the sub menu has been reversed.

REMOVED BUGS:

Concerning the management of folders and copies, several additional tests have been added. In the previous software depending on different manipulations, it was possible to copy into the working folder resulting the loss of an index.

When erasing a folder, sometimes the size, number of indexes in the other folders could be wrong.

(OMS 31-808 & 31-809)
NAGRAVISION SA
NOV 15 2004