
ERRATUM SERVICE MANUAL

Please add in your service manual the next item:

- *Page 20:*

Item 22: Tray switch 023-00610-001 1

