



Circuit Change

PROBLEM: *There is a small residual output when the volume is set to minimum.*

CAUSE: *Not enough attenuation of the volume control when the input level is high.*

SOLUTION: *Increase the attenuation of the volume control by changing the value of R514 and R614 from 3R0 to any value up to 3R6.*

PRODUCTION:

This circuit change has been implemented in production from serial number: H08C37000055.

Contact:

NAD Electronics International
633 Granite Court
Pickering, ON Canada L1K 3K1
Voice: 905-831-0799 FAX 905-837-6357
NAD@www.NADelectronics.com