

---

## **Preset memory circuit change**

---

***PROBLEM:*** When a frequency of 102.5MHz or higher is stored into preset 3 the unit may change this frequency to 12.8MHz less after receiving any remote command (102.5MHz becomes 89.2MHz). This occurs even with other brand's remote commands.

---

***CAUSE:*** This is a software bug.

---

***SOLUTION:*** The solution is to replace the CPU, this will keep the part number mentioned in the service manual: LC866448B (201).

---

***PRODUCTION:***

This modification has been implemented in production from serial number: G0XC42003201

---

**Contact:**

**NAD Electronics International  
633 Granite Court  
Pickering, ON Canada L1K 3K1  
Voice: 905-831-0799 FAX 905-837-6357  
NAD@www.NADelectronics.com**