

Circuit Change

PROBLEM: Original transformer for the L40 back light display was changed in production.

The first transformer was a 3 pin module inverter package. The second transformer is a 9 pin stand alone transformer. The part numbers for the two parts is shown below.

Order part according to the diagram below.

9 PIN TRANSFORMER

PART NUMBER#1806-2320-0
(new version)

3 PIN TRANSFORMER MODULE

PART NUMBER#1806-2217-0
(original in service manual)

Contact:

NAD Electronics International
633 Granite Court
Pickering, ON Canada L1K 3K1
Voice: 905-831-0799 FAX 905-837-6357
www.nadelectronics.com