

Circuit Change

PROBLEM: *The picture on from the RGB SCART output is not at optimum level.*

CAUSE: *The RGB SCART output level is low.*

SOLUTION: *Change R374, R375 and R376 from 75R to 62R.*

PRODUCTION:

This change has been implemented in production from serial number: A14L5502001

Contact:

**NAD Electronics International
633 Granite Court
Pickering, ON Canada L1K 3K1
Voice: 905-831-0799 FAX 905-837-6357
NAD@NADelectronics.com**