

Circuit Change

PROBLEM: When replacing the DSP board there may be a connector in backwards. Check the connector J101A on the DSP board, the two open slits of the connector should be facing outwards or away from the regulators on the DSP board.

SOLUTION : Using a screwdriver gently pry the white plastic moulded part of the connector from the DSP board. Reinstall the part with the open slits facing outwards.

The affected part is the DSP board ,part number PCB-N0910C-AC3.

Contact:

**NAD Electronics International
633 Granite Court
Pickering, ON Canada L1K 3K1
Voice: 905-831-0799 FAX 905-837-6357
www.NADelectronics.com**