



Numark[®]


Service Information


AXIS 9

www.numark.com









	R634	R625	R700	R701	R614	R607
AX358	1	1			1	1
AX359	1			1	1	1
AX375		1	1		1	1
CDN90						

3代,表該零件需插。

2002.7.1 追加 C647 and C648 追加 FTECH CONTROL LCU 動作 (良電機社)
C647 新製品に TR601
C648 新製品に TR606


Title				AXIS8, 9, CDM90			
Size	Number			Revision			
A2	BUFFER PCB (PC02024)			V03			
Unit	21-Mar-2005			94 2105	Sheet of	101	
File	E:\818081\1\CA6040030.sch			Drawn By	LUNG EN CHENG		

PITCH AND WHEEL RECALIBRATION PROCEEDURE


Occasionally you may find the pitch center position does not indicate 0% or the wheel may not respond as accurately or quickly as have experienced in the past. In this case we recommend recalibrating the unit for optimal performance.




Turn on the unit with no disc inserted.



Starting from center
Move your slider all the way negative
then all the way positive
then back to center



Spin the wheel clockwise
as fast as possible



While the wheel is spinning press the five
buttons indicated above and release



When proper calibration has been set
the BPM display will indicate "88"