

CONFIDENTIAL

**ONKYO**<sup>®</sup>

18 Park Way, Upper Saddle River, NJ 07458

*Tips & Tricks*

**No. 20060906**

**Date:** September 6, 2006

---

**Model: DTR4.6 / 5.6 /6.6/7.6 TX-SR573/TX-SR603X**

**Subject: XM ANT Jack**

**Symptom:** XM ANT JACK broken lose from PCB board.

**Solution:** ADD TRM Terminal support hold Xm Satellite ANT Jack mounting on board. Solder jump wires for connection see next page two pictures.

**Parts:**

Ref#	Description	Part Number
	TRM (NTM-1P243)	25060312
	Xm Satellite Ant Jack	25053104R2



