

CONFIDENTIAL



18 Park Way, Upper Saddle River, NJ 07458

*Tips & Tricks*

**No. 20060906**

**Date:** September 6, 2006

---

**Model: DTR4.6 / 5.6 /6.6/7.6 TX-SR573/TX-SR603X**

**Subject: XM ANT Jack**

**Symptom:** XM ANT JACK broken lose from PCB board.

**Solution:** ADD TRM Terminal support hold Xm Satellite ANT Jack mounting on board. Solder jump wires for connection see next page two pictures.

**Parts:**

| <b>Ref#</b> | <b>Description</b>    | <b>Part Number</b> |
|-------------|-----------------------|--------------------|
|             | TRM (NTM-1P243)       | 25060312           |
|             | Xm Satellite Ant Jack | 25053104R2         |
|             |                       |                    |



