

Last version: Bold-faced

Version	Circuit No.	Part No.	Description	Use	Label on IC	Reason	Application
Ver2.11.0001	Q7001	22241363	M30624FGFP	IC, Main	M01Z14A	Skipping when play Pearl Harbor etc. encoded by Extended Bitstream Parameter.	From Jan., 2002 Firmware of after service: VRGF0211.frm
		22241512	M30624FGAFP	microprocessor			
	Q7201	22241363	M30624FGFP	IC, Sub	M01Z14A		
		22241512	M30624FGAFP	microprocessor			
	Q728	22241457R3	MBM29LV004TC-90PTN	IC,1st DSP ROM	01828A		
		22241530R3	MBM29LV008TA-90PTN				
Q768	22241458R3	MBM29LV002TC-90PTN	IC,2nd DSP ROM	01828A			
	22241457R3	MBM29LV004TC-90PTN					
	22241530R3	MBM29LV008TA-90PTN					
Ver2.10.0001	Q7001	22241363	M30624FGFP	IC, Main	M01X29A	Noise when play a part DTS soft with DTS-ES Matrix 6.1 and Re-EQ ON.	From Nov., 2001
		22241512	M30624FGAFP	microprocessor			
	Q7201	22241363	M30624FGFP	IC, Sub	S01X29A		
		22241512	M30624FGAFP	microprocessor			
	Q728	22241457R3	MBM29LV004TC-90PTN	IC,1st DSP ROM	01828A		
		22241530R3	MBM29LV008TA-90PTN				
Q768	22241458R3	MBM29LV002TC-90PTN	IC,2nd DSP ROM	01828A			
	22241457R3	MBM29LV004TC-90PTN					
	22241530R3	MBM29LV008TA-90PTN					
Ver2.09.0001	Q7001	22241363	M30624FGFP	IC, Main	M01918A	No sound when repeat the operation of play and pause with a part DVD player	From Oct., 2001
		22241512	M30624FGAFP	microprocessor			
	Q7201	22241363	M30624FGFP	IC, Sub	S01918A		
		22241512	M30624FGAFP	microprocessor			
	Q728	22241457R3	MBM29LV004TC-90PTN	IC,1st DSP ROM	01828A		
		22241530R3	MBM29LV008TA-90PTN				
Q768	22241458R3	MBM29LV002TC-90PTN	IC,2nd DSP ROM	01828A			
	22241457R3	MBM29LV004TC-90PTN					
	22241530R3	MBM29LV008TA-90PTN					
Ver2.08.0001	Q7001	22241363	M30624FGFP	IC, Main	M01828A	Correction of Offset of delay time when PLII Movie	From Sep., 2001
		22241512	M30624FGAFP	microprocessor			
	Q7201	22241363	M30624FGFP	IC, Sub	S01828A		
		22241512	M30624FGAFP	microprocessor			
	Q728	22241457R3	MBM29LV004TC-90PTN	IC,1st DSP ROM	01828A		
		22241530R3	MBM29LV008TA-90PTN				
Q768	22241458R3	MBM29LV002TC-90PTN	IC,2nd DSP ROM	01828A			
	22241457R3	MBM29LV004TC-90PTN					
	22241530R3	MBM29LV008TA-90PTN					
Ver1.14.0000	Q7001	22241363	M30624FGFP	IC, Main	M00908A	Can't memory the contains of listening mode when set the Lock Setup to Locked.	From Sep., 2001
		22241512	M30624FGAFP	microprocessor			
	Q7201	22241363	M30624FGFP	IC, Sub	S00908A		
		22241512	M30624FGAFP	microprocessor			
	Q728	22241457R3	MBM29LV004TC-90PTN	IC,1st DSP ROM	00223A		
		22241530R3	MBM29LV008TA-90PTN				
Q768	22241458R3	MBM29LV002TC-90PTN	IC,2nd DSP ROM	00223A			
	22241457R3	MBM29LV004TC-90PTN					
	22241530R3	MBM29LV008TA-90PTN					