

# Service Manual

COMPACT  
disc  
DIGITAL AUDIO

SHOCK  
WAVE



MASH<sup>\*</sup>  
multi-stage noise shaping

※ • MASH is a trademark of NTT.

Portable CD Player

## SL-SW411C

Colour

(K) ..... Black Type

Areas

PC ..... Canada.

Please file and use this manual together with the service manual for Model No. SL-SW205/SW405/SW415, Order No. AD9703062C1.

- Notes: • This simplified service manual is provided to indicate the main differences between the original model No. SL-SW205/SW405/SW415(P,PC) and the subsequent model No. SL-SW411C(PC).  
In this service manual, a comparison is drawn between the above-stated 3 models and the SL-SW405(PC).  
• Refer to the Packaging of this service manual.

### CHANGES

#### ■ Change in Replacement Parts List (SL-SW205/SW405/SW415 Service Manual of pages 35, 36.)

- Notes: \* Mentioned in this parts list is only those different from Model No. SL-W405(PC). All other parts are the same as for SL-SW405(PC).  
\* Important safety notice:  
Components identified by Δ mark have special characteristics important for safety.  
Furthermore, special parts which have purposes of fire-retardant (resistors), high-quality sound (capacitors), low-noise (resistors), etc. are used. When replacing any of components, be sure to use only manufacturer's specified parts shown in the parts list  
\* [M] indicates in Remarks columns parts that are supplied by MESA.

Ref No.	Change of Part No.		Part Name & Description	Remarks
	SL-SW405(PC)	➡ SL-SW411C(PC)		
CABINET AND CHASSES				
5	RFKJLSW405PA	RFKJLSW411C	BOTTOM CABINET ASS'Y	[M]
6	RYF0409G-A	RYF0409E-K	CD COVER ASS'Y	[M]
34	RQLA0393	RQLA0394	PLUG CAUTION LABEL	[M]
PACKAGING				
P5	RPK0924	RPK0946	PACKING CASE	[M]
P7	RPQ0638	_____	_____	[M] Deletion
P9	_____	RPQ0820-1	SPACER	[M] Addition
P10	_____	RPQ0821	SPACER	[M] Addition

Δ WARNING

This service information is designed for experienced repair technicians only and is not designed for use by the general public. It does not contain warnings or cautions to advise non-technical individuals of potential dangers in attempting to service a product. Products powered by electricity should be serviced or repaired only by experienced professional technicians. Any attempt to service or repair the product or products dealt with in this service information by anyone else could result in serious injury or death.

# Panasonic<sup>®</sup>

© 1997 Matsushita Electric Industrial Co., Ltd.  
All rights reserved. Unauthorized copying and distribution is a violation of law.

Ref No.	Change of Part No.		Part Name & Description	Remarks
	SL-SW405(PC)	➡ SL-SW411C(PC)		
A				
A1	_____	RQT3518-C	INSTRUCTION MANUAL (CAR MOUNT KIT)	[M] <IA> Addition
A1	_____	RQT3825-P	INSTRUCTION MANUAL (CAR MOUNT KIT)	[M] <IB> Addition
A3	RFEV701P-A1S	RFEV701P-K1S	STEREO HEADPHONES	[M]
A4	SQX9131	RQCB0832-1	SERVICENTER LIST	[M]
A5	SQX7185	RQA0132	WARRANTY CARD	[M]
A7	_____	SH-CDC2PPY	CAR ADAPTOR	[M] Addition
A7-1	_____	XBA1605NBAU	FUSE, 500mA (IN CAR ADAPTOR)	[M] Δ Addition
A8	_____	SH-CDM8ASY-K	CAR STEREO CASSETTE ADAPTOR	[M] Δ Addition

**Note:** ● “The <IA>: English and French, <IB>: English” marks in Remarks indicate language of instruction manual.

## ■ Packaging (SL-SW205/SW405/SW415 Service Manual of page 37.)

