




F LOADING MOTOR CIRCUIT (P.C. Board: on page 44)




B TRAY MOTOR CIRCUIT (P.C. Board: on page 44)



G SENSOR CIRCUIT (P.C. Board: on page 44)



C POWER SWITCH CIRCUIT (P.C. Board: on page 42)



D PHOTO TRANSISTOR CIRCUIT (P.C. Board: on page 44)



E OPERATION CIRCUIT (P.C. Board: on pages 43,44)

