

# aiwa

**AIWA CO.,LTD. UTSUNOMIYA FACTORY**

2620, TOKUJIROU-MACHI, UTSUNOMIYA-SHI,TOCHIGI 321-21,JAPAN

## SERVICE TECHNICAL INFORMATION

UTSUNOMIYA, APR. 17,1995

REF.NO. SI-95-002

CUSTOMER RELATIONS & SERVICE DIV.

MODEL : AM-F1 , AMD-100

SUBJECT : Notes for replacing the mini disc pickup ASSY

CONTENT : For the above models, always replace the ASSY whenever there is a faulty pickup.  
Also, when disassembling or assembling the set, do not disassemble the pickup ASSY.

The MD Pickup ASSY has been precisely adjusted at the factory so that the Over Write Head and the pickup join together on the optical path.

