

# DIAGRAM

S	1.	2.	3.	4,5,6,7.	50, 8,9, 10.	16,11,12,13,14,15,17,18,19,20,21.	22,23,24.	25,26,27,28,29,30.	31,32.	33,34,35,36,37,38.	39,40.	41,42,43,44,45,46,47,48,49.	S														
C	1.	3,2.	76.	5.	7.	8.	10.	9.	12.	13.	15,16,17,20.	22.	34,35,36.	43,44.	46.	47.	49,50,51.	53.	55,56.	57.	59,60.	61,62.	75,63,64,65.	66.	70,71.	74.	C
C		4.	6.		11.	14.	18.	21,19,23.	27,24,29,31.	32,26.	30,33.	37,40,40a.	38,39,42,41.	45.	48.	52.					58.			67,68,69.	72.		C
R		1.							10.	55.		19.	25.	29,30.	29,30.	34,33,35.					38,39.			45,46.	47,48.	51,52,53.	R
R		2.	3.	4.	5.	6.	8.	7,13,9.	11,12.	14.	15.	18,20,16,17,21,24,22,23.	26,27,28.	31.	32.	36.					37,40.	41,42.	43,44.	50,56.	49,54.		R

