
Service Documentation

RevD 16/05/08

Contents

1. Revision Summary
2. Circuit Diagrams
 - a. Power Amp Module
 - b. Input Board
 - c. LED Board
 - d. PSU Board

Revision Summary

09/03/05

CD6330 RevB to RevC

C4, C24 changed from 100pF to 47pF

Serial Numbers affected

50370001 and later

16/03/07

CD6334 RevC to RevD

R1 changed from 100k to 47k

C5-6 changed from 47uF to 100uF

Serial Numbers affected

A804XXXXX and later

16/05/08 RevD

CD6330-1 RevD to RevE

Added thermal switch to bridge rectifier

Removed PCB overlays

Serial Numbers affected:

A806XXXXX and later

Parts Duplicated for Channels 1 & 2 (3 & 4)

AMIS480P POWER AMP


CD6330-1

Revision E

Date 16-MAR-2008

File C:\ATC\AMIS480P\AMIS480P.dtb

Drawn By: CWR



Title		Revision	
AMIS804P INPUT		CD6332-1	
Size	Number	Date	Sheet 1 of 1
A3		11-Jan-2005	
File	C:\ATC\AMIS804P\AMIS804P.dtb	Drawn By	C.Tor

