

SERVICE TECHNICAL REPORT

KENWOOD

KENWOOD CORPORATION

1/1

STR No. B143-97-029E

DATE : December 15, 1997

GENRE : HOME AUDIO

MODEL : 1090MD

SUBJECT : Substitutive information of service manual

1090MD is modified from DM-9090 and will be sold in U.S.A (K type).
 Service manual will be not made as there is less different parts.
 Please refer to DM-9090 service manual (B51-5387-00) if you want to know more.

Ref.No.	Add-ress	New Parts	Parts No.	Description	Desti-nation
612	2F	*	A60-1257-02	Panel ASSY	
-		*	B60-3495-00	INSTRUCTION MANUAL	
-			B46-0328-03	WARRANTY CARD	
-			B46-0336-03	WARRANTY CARD	
632	1H		E30-2650-05	AC POWER CORD	
-		*	H50-2555-14	ITEM CARTON CASE	
POWER SUPPLY (X08-2840-01)					
F1			F50-0067-05	FUSE (SEMKO) (125V 1.25A)	

WRITER T. Kumagai APPROVED E. Hirako

CAUSE :

Repair code A(S):	B:	C (P):	D (C):
Index Code	Information 1:	2:	Symptom 1: 2:
Parts stock	<input type="checkbox"/> Yes <input type="checkbox"/> No	Availability	M D
Prod. change	Lot	S/No..	
Application	<input type="checkbox"/> All repair units <input type="checkbox"/> Defectives only <input type="checkbox"/> Refurbish	KPC	<u>K. SAKURA</u>
Distribution	<input type="checkbox"/> KSJ <input checked="" type="checkbox"/> KPC <input type="checkbox"/> CS DIV. <input checked="" type="checkbox"/> SUBSIDIARY SALES	<input checked="" type="checkbox"/> IMD <input type="checkbox"/> GENERAL AGENT	<input checked="" type="checkbox"/> SHOW ROOM

Information : 1: Countermeasure, 2: Parts, 3: S/M, 4: Noise (Car only), 5: Repair, 6: Genuine (Car), 7: μ -com/software, 8: I/M, 9: etc.
 Symptom : Symptom code of Repair Code List