



## **Service Bulletin**

No.: MZ06-028


Date: December 18, 2006

Model: PM6001 PM7001, PM8001

**Subject:** Service part addition.

**Symptom:** The part number of Main Microprocessor (Q201) software was added to the Service manual as a spare part. (\* Microprocessor needs writing software, when a microprocessor (Q201) is replaced).

### Solution:



Attention: Don't start the update from the zipped file. Please copy it to your PC and unzip before using.

#### **CONFIDENTIALITY NOTICE:**

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.

## Parts:

Ref#	Description	Part Number
new	00M14AJ49903_PM6001_7001_8001.zip	00M14AJ499A03

# **Serial Number Range:**

ΑII