



Service Bulletin

No. : MZ05-022

Date: January 8, 2007

Model: SA8260, SA-17S1

Subject: Cannot playback specific Super Audio CD Disc.

Symptom: Can not read the invisible watermark of specific Super Audio CD:
R.Strauss /Alps symphony (UCGG-7011).


Solution: L110 Ferrite Core has been changed to a Chip Resistor (100 OHM)
on the PV16-SERVO PWB.

Parts:



Ref #	FORMER		NEW	
	Description	Part Number	Description	Part Number
L110	FERRITE CORE	FC90020100	100 OHM +- 5% 1/16W CHIP 1608 TYPE RESISTOR	00MNN05101610

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.



PV16-SERVO PWB



L110

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.