



Service Bulletin

No.: MZ07-086

Date: September 20, 2007

Model: SA-7S1, SA-11S1, SA15S1, SA7001, SA8001

Subject: The software used for the first edition, Non-RoHs-compliant pickup.

Symptom: This Software (firmware) was used for the mass production for Non-RoHs-compliant pickup.

Solution: Please refer to the service manual for "How to update Software".

*Flash ROM IC731 (With software). Usually, no need to write-in this software. The replacement parts of these IC's have already been written with the software.

The update can be performed with a DVD-R disc. Please execute it as per the procedure laid down in the Service Manual for each model.

To be written in the DVD-R are the following five types of files:

- 1. Ds1hnvdy.cfw
- 2. FGSA7001.bin
- 3. FGSA7002.bin
- 4. FG-SA11.cfw
- 5. FGSA11 7.bin


The format is ISO Joliet mode 1. The files can be in a random order.

CONFIDENTIALITY NOTICE:

How to identify pickup:


RoHs compliant pickup

Non-RoHs-compliant pickup



NOTE: Some types of writing software cause the unit to fail to read the files. If it occurs, use the update disc (Part no: 90M-SA0002DVD).

e.g. When using the "NERO" CD writing software, set the Character Set to "DOS".



CONFIDENTIALITY NOTICE:

Parts:

Ref#	Description	Part Number
NA	Update disc	90M-SA0002DVD

When the writing has completed, please check the version number.

Model	Version	Remarks
SA7001	V06.18	The version is determined by the microprocessor the unit is
	V40.00	equipped with. Please confirm that the version is one of these
	V41.00	three.
SA8001	V06.18	The version is determined by the microprocessor the unit is
	V40.00	equipped with. Please confirm that the version is one of these
	V41.00	three.
SA-11S1	V07.23	The version is determined by the microprocessor the unit is
	V42.00	equipped with. Please confirm that the version is either of
		these two.
SA-15S1	V08.23	The version is determined by the microprocessor the unit is
	V43.00	equipped with. Please confirm that the version is either of
		these two.
SA-7S1	V42.00	