



**Service Bulletin** 

**No.:** MZ05-047

Date: January 3, 2007

Model: SR4500

**Subject:** Correction of the Service Manual, Electrical parts list.

**Symptom:** The parts numbers for Q653, Q654, Q655, Q661, Q804 and Q807 outlined in the SR4500 Service Manual are incorrect (on page 91).

**Solution:** Use the part number listed below when ordering replacement parts.

## Parts:

Ref #	FORMER		NEW	
	Description	Part Number	Description	Part Number
Q653,	2SB1560	90M-HT200441R	2SB1560	90M-HT200440R
Q654,		90M-HT200442R		
Q655,		90M-HT200443R		
Q661,		90M-HT200444R		
Q804 and		90M-HT200445R		
Q807		90M-HT200446R		

## **Serial Number Range:**

ΑII

## **CONFIDENTIALITY NOTICE:**