

<b>marantz®</b> <b>SERVICE BULLETIN</b>		Date: 24-Oct.-2005	Model: ST7001/N1B/N1S
		Page: 1 / 1	REF.NBR: MZ05-038
Level		Application:	
★		See below	
Subject: Correction of the Service Manual, Electrical parts list.			
Int.ref:			

**[REASONS]**

The parts number for POS. NO **IC300 MAIN PWB** mentioned on the ST7001/N1B/N1S's Service Manual is in correct. (Service Manual page 51)

**[CORRECTION PARTS LIST]**

OLD NEW	POS. NO.	VERS. COLOR	PART NO. (FOR EUR)	PART NO. (MJI)	PART NAME	DESCRIPTION
<b>OLD</b>	<b>IC300</b>		<b>00D9630226103</b>	<b>00D9630226103</b>	<b>U-PRO</b>	<b>MB90F352PFM-G (128K,4K) LQFP64</b> <b>Factory code no. J020903520010S</b>
<b>NEW</b>	<b>IC300</b>		<b>90M-HS46BWX0R</b>	<b>90M-HS46BWX0R</b>	<b>U-PRO</b>	<b>MB90F352PFM-G (128K,4K) LQFP64</b> <b>Factory code no. J020903520010S</b> <b>ST7001 MPxxx</b>

Approved by **N.Sensui** Written by **S.NAGAO**