

marantz[®]

Service Bulletin

No. : MZ10-003

Date: May 11, 2010

Model: UD9004

Subject: Modification of the "FE/SACD UNIT"(8U-310010).

This is for your Information only.

Details: We moved the attached parts from pattern side to the component side of the PWB "FE/SACD UNIT" (8U-310010).

Serial Number Range:

We will apply the above modification to the production models.
(Full-digit)

*****000171 ~

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.