



To bypass input xfmr:
Disconnect wires at points
marked by "X".
Install jumpers where indicated

D-155846-0

MI-9377-A

MI-9377-A POWER AMPLIFIER
SCHEMATIC DIAGRAM

2C3-24.10
7-29-53
PAGE 6 OF 6