
ERRATUM SERVICE MANUAL

Please correct in your service manual the next item:

- *Page 24:*

Item 4: Main Motor MMI-6H2LWK

Please note that the given part number in the service manual is not correct; it refers to a 613 motor.