



**SPECTRAL DMC-10
SYSTEM BOARD**
SPECTRAL AUDIO ASSOCIATES 1981
REV 2

SERVICE ADJUSTMENTS:

- #3 DC OFFSET - ADJUST FOR 0.01VDC ON EITHER END OF R124 (224)
- #4 BIAS - ADJUST FOR 2V ± 0.2V ACROSS R120 (220)
- #5 DC OFFSET - ADJUST FOR 0.01VDC ON EITHER END OF R145 (245)
- #6 BIAS - ADJUST FOR 2V ± 0.2V ACROSS R144 (244)

NOTES:

1. COMPONENTS PREFIXED BY 1XX LEFT CHANNEL. COMPONENTS PREFIXED BY 2XX RIGHT CHANNEL. CONNECTOR PHINOUTS - L (R).
2. PHONO LOADING - RESISTOR SELECTED TO MATCH INPUT REQUIREMENTS.