Simplified

AV Control Stereo Receiver

DOLBY SURROUND

Colour

	(K) .	 BI	ack T	уре

Area Suffix for Area Colour Model No (PC) Canada (K)



 $Manufactured\,under\,license\,from\,Dolby\,Laboratories\,Licensing$ Corporation. Additinnally licensed under one or more of the following patents: U.S. numbers 3,632,886,3,746,792 and 3,959,590; Canadian numbers 1,004,603 and 1,037,877. "Dolby" and the double-D symbol are trade marks of Dolby Laboratories Licensing Corporation.

Please file and use this Service Manual together with the Service Manual for Model No. SA-AX720 (P,PC) Order No. MD9712150C1.

Note: This Simplified Service Manual is provided to indicate the main difference between the orginal Model No. SA-AX720 (PC) and the subsequent Model No. SA-AX620 (PC).

Change In Replacement Parts List

		Change of Parts Number				
Ref. No.	Description	SA-AX720PC-K		SA-AX620PC-K		Remarks
PAC	KING MATERIALS					1
P3	PACKING CASE	RPG3679	[M]	RPG4018	[M]	Changed
ACC	ESSORIES					
A1	REMOTE CONTROL	EUR646463	[M]	EUR646475	[M]	Changed
A5	O/I BOOK	RQT4208-P	[M]	RQT4528-P	[M]	Changed
A5	O/I BOOK FOR REMOTE	RQT4209-P	[M]	RQT4529-P	[M]	Changed
A5	O/I BOOK	RQT4210-C	[M]	RQT4530-C	[M]	Changed
A5	O/I BOOK FOR REMOTE	RQT4211-C	[M]	RQT4531-C	[M]	Changed

⚠ WARNING

This service information is designed for experienced repair technicians only and is not designed for use by the general public. It does not contain warnings or cautions to advise non-technical individuals of potential dangers in attempting to service a product. Products powered by electricity should be serviced or repaired only by experienced professional technicians. Any attempt to service or repair the product or products dealt with in this service information by anyone else could result in serious injury or death.

Technics[®]

© 1998 Matsushita Electronics (S) Pte. Ltd. All rights reserved. Unauthorized copying and distribution is a violation of law.

MESA Printed in Singapore G980400800 L