



Service Bulletin

No. : MZ06-031

Date: July 28, 2008

Model: CC4001

Subject: Correction of the Service Manual, Electrical parts list.

Symptom: The Transformer part number (POS. NO.47) mentioned on the CC4001's Service Manual is incorrect. (Service Manual page 30)

Solution: Use the NEW part listed below when ordering a replacement transformer.

Parts:

Ref #	FORMER		NEW	
	Description	Part Number	Description	Part Number
47	TRANSF.	90M- TS002740R	TRANSF.	90M- TS002780R

Serial Number Range:

All

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.